INDUSTRIAL WAS INVESTIGATION AND SURVEILLANCE PATUS REPORT

FIRM NAME OZARK HARDWOOD CO.
ADDRESS 1412 West Florida TELEPHONE 8660879
PERSONNEL CONTACTED Wen H Chesteen Pres Position St. Joseph M6
Phillips, Patter See Position
David W. Duncan Treas Position St. Joseph Mo
ACTION INITIATED BY:
1 2-31-72 - Instigation by Corson + Lymen of discharge
to creck a camples taken
2) 3-9-72 - analysis of Sangles
3) 11-2-72 - Letter from Cuswell about abalement
4) 11-8-72 - Letter from 5. Decker about about
3 choduly.
5)-11-13-72 - analysis of Samples - plant b)-11-14-72 - analysis of Samples - Health 7)-12-7-72 - Letter to Phil Platler from arowell
W-11-14-72 - anduris of Sandles - Health
7) - 12-7-72 - Letter to Phil Platler from aswell
about meeting
5)-3-27-73- Inspection by B. Corson, Phyman, M. Abot.
NAA
9)-3-30-73 - Letter Som Jerry King to Phil Platter
about hook-up to santary source

November 8, 1979

Mr. M. O. Carr Ozark Hardwoods Inc. 1412 W. Florida Springfield, MO

Dear Mr. Carr:

As you are probably aware, the Federal Water Pollution Control Act as amended in 1972 and the Clean Water Act of 1977, established a national pretreatment policy aimed at controlling the discharges from industrial users into municipal systems. The Acts call for two sets of pretreatment standards. The first, General Pretreatment Regulations, established a set of prohibited discharges for all users. The second is being and will continue to be promulgated for individual industrial categories and sub-categories and will specify quantities or concentrations of specific pollutants which may be introduced into a municipal system by certain classes of industrial users.

The General Pretreatment Regulations were issued on June 26, 1978 and proposed amendments were published on October 29, 1979 with comments on these amendments accepted until November 28, 1979. Specific pretreatment standards for the Timber Products Processing Point Source Category were proposed October 31, 1979. Comments for these proposed regulations will be accepted on or before December 31, 1979.

Your company is or may be subject to these regulations or may become subject in the future. The applicability of the specific category regulation is determined by the type of business operation that a company is engaged in. It is not necessarily limited to those companies whose primary Standard Industrial Classification is identical to the classical textbook definition may have broad application to any similar operation within a firm which generates a like waste.

Enclosed for your review, please find copies of the Federal Register of June 26, 1978, General Pretreatment Regulations, October 29, 1979 General Regulation proposed amendments and October 31, 1979, Timber Products Processing Point Source Category regulations. If we may be of further assistance to you or can answer any question, please do not hesitate to call.

Yours truly,

Charles H. Criswell Associate Sanitary Engineer Chief, Water Pollution Control

CHC/3s

Enclosure: (3)

ce: Mr. Frank J. Dolan, Missouri Department of Natural Resources Mr. Ronald D. McCutcheon, Environmental Protection Agency Surveillance and Enforcement File Pretreatment File

August 17, 1977

Ozark Hardwoods, Inc. 1412 West Florida Springfield, Missouri 65803

Dear Sirs:

This office was contacted on the above date concerning a discharge from your property. Upon investigation the substance was found to be a water-soluble solvent used in your milling operation.

Personnel at your plant were contacted and agreed to clean up the spill with sawdust. Later inspection of this cleanup showed that your personnel did an excellent job. We would like to thank you for your cooperation in this aspect of the operation.

As you are probably aware, there are stringent Federal, State and City laws pertaining to the discharge of any petroleum-based products, such as the abovementioned solvent. Although the material did not reach a waterway in this instance, it could have reached a waterway if a more substantial amount of runoff had contacted the spill.

If this sort of spill should happen again, you would be well-advised to contain it immediately--before it leaves your property. Since your operation provides a considerable quantity of sawdust, it should present no problem to use this sawdust for containment and for soaking up the material.

If this office can be of further assistance or if you have any questions, please do not hesitate to call.

Sincerely,

John T. Witherspoon Water Pollution Control Inspector II Surveillance & Enforcement

JTW:pg

cc: Mr. John R. Nixon, Regional Administrator, Missouri Department of Natural Resources
Public Works File
Surveillance & Enforcement File

CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

ATTENTION OF Memo to file	DATEAugust 17, 1977
DEPARTMENT	

Re: Ozark Hardwoods, Inc. 1412 West Florida Oil Spill

This office was contacted about 11:20 a.m., 8-17-77, concerning a milky substance in the street near Florida and Nettleton. Wayne Latimer and I responded to the call and found the substance coming from the above establishment. The material had run in the street clear to the corner of Atlantic and Newton. I contacted the plant foreman and advised him of the necessity to cease this discharge. He stated that they were repairing a milling machine and the substance, a water-soluble solvent (Satisol by ARCO), had escaped onto their lot. The problem was complicated by the fact that recent rainwater greatly diluted the material and caused it to be washed out of their lot. He agreed to apply sawdust to the material and did so over the entire course of the spill. He was also to contact Ed Sears at DNR. Ozark Hardwoods personnel did an excellent cleanup job and prevented the substance from entering the storm sewer. A City street sweeper will clean up the remaining sawdust.

1412 W. FLOR 104

*ca. 15 gallons

John T. Witherspoon

CITY OF SPRINGFIELD, MISSOUR. DEPARTMENT OF PUBLIC HEALTH AND WELFARE GENERAL SANITATION SECTION

Date 4-25-75	(Fill in this space if illness occurred)
Time A.M., P.M.	No. persons illSymptoms
Lab. No	Time of ingestion Time of onset of symptoms
Sample submitted by: Robert Corro	
Name Ozark Hardwood	
Address	, Missouri
Sample of waste water	Perishable () Non-perishable ()
Condition of sample on arrival: Satis Name of Manufacturer poly cult (If not same as above)	factory () Unsatisfactory () Iced ()
(22	
Address	, Missouri
Reason for analysis infulitor	inly
TESTS TO BE RUN:	
Chemical & Physical Common Poiso (Eggs & Larvae) (), Insect fragment Starches or cerals (), Filth (),	ons (), Federal Standards (), Insects (), Sulphites (), Preservatives () Other (),
Bacteriological Total Count (), Coliform (), Oth	ier
	Sample received by
LABORATORY RESULTS & CONCLUSIONS: Analyst	Jembella Date 4-25-75
Sample is slightly in	hibitory to Bacillus subtilis

(Use back for additional information)

INDUSTRIAL WASTE SURVEY

Plant:	Ozak	Hardwoo	Pipe Size:	Dat	e: 4-24-75
Sample No	. <u>Time</u>	Meter Rea	ding Depth of	Flow Volume	Condition of Flow
1					
2					
3					
4					
. 5		94 /	u Conpose	to	
6		0,1 11	To the		
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17	1				
18	_				
19					
20					
21					
22					
23					
24					
				<u></u>	

Total 5 day B.O.D. 900 Meyle Total S.S. 23 Might Co 732 Might Cr 760 Might NH3.N 0.23 Might PH = 6.50

5.63 # per 100 ft.³
0.14 # per 100 ft.³



City Hall 830 Boonville Avenue Springfield, Missouri 65801 417-865-1611

March 30, 1973

Mr. Phil Platter Ozark Hardwood Company 1412 West Florida Street Springfield, MO 65803

Plumbing Code Violation Section P802.0 SUBJECT: Storm Water Drainage to Sewer Prohibited

Reference: Letter to you dated December 7, 1972, subject above from Mr. Charles Criswell.

Dear Mr. Platter:

I want to thank you very much for your time and courtesy in meeting with me and others this morning. In accordance with our conversation this morning, a determination has been made regarding your connection of Industrial Waste to the sewer. In Mr. Criswell's letter to you he indicated that the waste would be acceptable for discharge into the sanitary sewer. He did not specify any particular method for accomplishing this.

After reviewing the Plumbing Code and discussing the matter with Mr. Criswell. I have determined that there is a Plumbing Code violation by allowing storm water to enter the sanitary sewer. Accordingly, appropriate remedial action should be initiated to bring the system into compliance with Section P802.0 of the Plumbing Code.

If you desire any assistance regarding interpretation of the Plumbing Code, please let me know and I will be happy to assist.

Sincerely.


Jerry King, P.E.

Public Works Department

JK/dw

cc: Harry Lampe, Director of Public Works Leonard Sims. Plumbing Inspector

Ozark Hardwood Co. 3-27-73 10:30 A.M. Ispection by B. Corson, R. Lyman, G. Pabet of facilities are pictured in drawing below



December 7, 1972

Mr. Phil Platter Ozark Hardwood Company 1412 West Florida Street Springfield, Missouri 65803

Dear Mr. Platter:

Thank you for the courtesy extended when Joe Allen and I visited your plant recently. Since that time, we have conducted various laboratory analyses on the waste discharged from your steam treatment of wood. As I indicated to you, we were most concerned with a fairly high concentration of phenol and phenolic compounds. These compounds are inhibitory to biological processes and we were able to confirm their action with toxicity analyses. In addition, phenols characteristically promote taste and odor problems, especially in conjunction with chlorination. However, based on the discharge volume data you have supplied, we have determined that your waste would now be acceptable for discharge into the sanitary sewer. Please advise us if in the future your volume of discharge greatly increases or you contemplate a change in your process.

If we may be of any further assistance or may answer any questions, please feel free to call on us at any time.

Yours very truly,

Charles H. Criswell Chemist and Aquatic Biologist Industrial Waste Surveillance & Enforcement

CHC:cc

cc: Mr. Joe Allen, Coordinator, Air Pollution Control Authority

Mr. Harold Bengsch, Superintendent of Environmental Public Health Mr. Steve Decker, Regional Engineer, Missouri Clean Water Commission

Mr. Dick Paul, Investigation Section, U.S. Corps of Engineers

To	1003	C Lawr	<u> </u>
	Time	By 8101	
Whit	e Vou T	Were Out	!
Mr			
of			
☐ Telephoned ☐ Will Call Ago ☐ Please Call		☐ Called to ☐ Wants t ☐ Rush!	See You o See You
Phone			<u> </u>
		Lewood	
		elution	
		2,740	
200	~ V.	200	N-
	19.0	7 11	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	delul		}
1.0		2000	ر لالور
2,7	40 4	2,877	<u> </u>
To Gr	usuu		
Date 11/10	Time/ 15	By 66	صر د
While	21 1	By 66 Vere Out	
While	You t	Vere Out	.) [
Mr. Tlue	100,	Thel	
of Ozar	LX	devos	U
☐ Telephoned ☐ Will Call Ago ☐ Please Call		☐ Called to : ☐ Wants to ☐ Rush!	
Phone Sa	66-08	79	
Message			
Said	they	selle	//
an set	epile	d) 3 Z	55
gal xe	V day	dysto	aen
when	oper	ting	
Zanen	s d	ils	7
assiste	Luce	unda	(A
Two to to	tale	Do to	Dew .
- Epided - St.	WARE	0	Course Tours.

0 /
Ri Lawson 1019 W. Crestview
1019 W. Crestiven
883 - 8258 SMIT
While You Were Out
THO SABOA MOO BILLIAN
Mr.
31 V I
10
☐ Telephoned ☐ Called to See You
☐ Will Cail Again ☐ Wants to See You
Please Call Him Rush!
Phone
Message Examp XL Europe
William OF I T
The state of the s
44400120
a to the same of t
0946
8/6/ 5 29
8/61 2097
The state of the s
20 mm
a fileran
in the second
10
Date /// 2 Time/ 15 By 66
0 110 100 110
While you Were Out
The second
W. Walsh all .
Mars & 51 de as 11
Dagger State of the
Talephoned Called to See You
. Will Call Again Wants to See You
G-Please Call Him Rush
Phone 866-0879
the same of the sa
Message
Asido they solled
That for Ohand. Etz.
Later and the later and with the same
and see 12 min a second as seen
secure - Entreton & Sunth Plant
war a formand in samon
The a put declared in sandary
The a pur ductioner in santon
The of your direction in sandons
The of just directed in saulang
Marine : Mays - (181) - shill and shill

```
Ozark Hardwood
                                           3-5 gal/day
0.000\ 005\ x\ 8.34 = 0.000\ 041\ 70\ x\ 1\ 000\ ppm = 0.041\ 7\ lbs/day
                                      2 000
                                                 = 0.0834
                                      2 400
                                              11
                                                 = 0.100+
                                      2 500
                                                 = 0.104+
                                      3 000
                                                 = 0.125
                                      4 000
                                                 = 0.167
                                      4 450
                                              11
                                                 = 0.1856
                                              11
                                                 = 0.2085
                                      5 000
                                             11
                                     24 000
                                                 = 1.0
        3610 mg/1=0.151
                            lbs/day
Ct
                  =0.0045
Ci
         108
        3502
                 =0.146
Co
BOD
        4450
                 =0.186
SS
         620
                 =0.026
                                      47 000
         139.5
NH3-N
                 =0.005 8
                                      58 000
                                               48 670
P04
           9.5
                  =0.000 4
                                      41 000
Phenol
                                                          0.24 \text{ ppm} = 0.000 \text{ } 01 \text{ } 1\text{bs/day}
                                                          15. ppm = 0.000 \ 1 \ 1bs/days (10)
           6.31
                                                                      ,0.001
                                                                                 1bs/days (100)
рΗ
                                                                                 1bs/days (1000)
                                                                       0.01
                                                                                 lbs/days (10000)
                                                                       0.1
                                                                       1.0
                                                                                 lbs/days (100000)
                                                                       1.0
                                                                                 lbs/274 yrs.
Phil Platter, Ozark Hardwood 11-9-72
Wants to put discharge in sanitary sewer
check Phenols & Terpines
```

Mr. Lafferty - called M.C.W.C.- 11-9-72
"Creosote" in ditch above spring
W. of Barn (Vich's)
came down with storm water?
checked by E. Sears, B. Corson, R. Lyman
Pete Gaskin - Moss America - wants sample 11-10-72

Wash wats water once week or wet dry lumber 20 ppm 5

10 gal /day

dilution to 1 MGD (NWP) 0.0002 mg/e

2 MGD 0.000 1 Mg/R acceptable, 0.5 mg/e

SS 620 - 48 670 = 2#/day × 78.5

Cone . 24 units

4450 - 349 325

140 10 990

9.50 7458

Inhibited BOD . 2% 1987 .1% 2809 27-28

.05% 3425 27.41

3610 283 385 285000 #2 day 280 ow 12#/deg 3502 2 280 000

Projected BOD -- - 350 000: 15# day @5

350000 15 day

11000 ,5#/day

7 500 ,3#/du

350 000

(@15 mgl = 0.0000625 #day

.000 0417

15 # day

CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

ATTENTION OF				
ATTENTION OF			DATE	
		143		
DEPARTMENT	1.4	重 致 初日	T. 2.	

Rev Herbert Hillme
707 w Portland St
707 w Portland St
865-1335
1559 S Grant
865-1335

Jump pump disch to lot obe
Sump pump disch to lot obe
Sump pump disch to put
There on saintary but your
North on saintary to do that work.

Not have approval to do that work.

869 3581

SIGNED.....

CITY OF SPRINGFIELD, MISSOURI DEPARTMENT OF PUBLIC HEALTH AND WELFARE GENERAL SANITATION SECTION

Date 11-14-72	(Fill in this space of illness occurred)
Timo 9/30 A.M., P.M.	No. persons illSymptoms
Lab. No	Time of ingestion Time of onset of symptoms
Sample submitted by: Harry Criswell	
Name OZARK HARDWOOD COM	PANY
Address 1412 W. Florida	, Miscourl
Semple of landwood extract flu	Perishable () Non-perishable ()
	sfectory () Unsetisfactory () Iced ()
Hame of Manufacturer Ozuk (If not same as above)	Hardwood
Address	, Missouri
Reason for analysis <u>investig</u>	ative
Mests to be run:	*
Charical & Physical Common Poise (Mggs & Larvao) (), Insect fragment Starches or cerals (), Filth (),	ons (), Federal Standards (), Insects ts (), Sulphites (), Preservatives () Other (),
Bacteriological Coliforn (), Oth	ner
,,,	
	Sampie received by
LABORATORY RESULTS & CONCLUSIONS: Analyst	Litambeth Date 11-14-72
PH - 6.1 Inhibitor - positive (c. 24 pc	

(Use back for additional information)

CITY OF SPRINGFIELD, MISSOURI DEPARTMENT OF PUBLIC HEALTH AND WELFARE GENERAL SANITATION SECTION

Date 11-14-72	(Fill in this space of illness occurred)
Time 9/30 A.M., P.M.	No. persons ill Symptems
Lab. No. miss	Time of ingestion
Scaled () Unscaled () Official () Unofficial ()	Time of onpat of symptoms
Sample submitted by: Harry Criswell	
Name	
Address	Missouri
Semple of landwood extract flu	Perishable () Non-perishable ()
~ //	sfactory () Unsetisfactory () Icad ()
Wame of Manufacturer Ozuk (If not same as above)	Hardwood
	, Hissouri
Reason for analysis investig	
SESTS TO BE RUN:	
Charical & Frysical Common Poise (Mega & Larvao) (), Insect fragment Starches or cerals (), Filth (),	ons (), Federal Standards (), Insects ts (), Sulphites (), Preservatives () Other (),
Bacteriological Coliform (), Oth	ner
	Sample received by
LABORATORY RESULTS & CONCLUSIONS: Analyst	Thankell Date 11-14-72
PH-6.1	
1 1/4 - positive (a -24 pc	mullin)
Insetrophotometer - pead at 2	250 my
phenol - > 54g/mlose back for an est	iditional information)
(greater than 5 ppm - est	finated at 15-20 PPM
1	1412 W. FLORID

CITY OF SPRINGFIELD, MISSCURI SOUTHWEST WASTEWATER TREATMENT PLANT LABORATORY ANALYSIS REQUEST

HECK ANALYSI	BOD ₅			PE	M			Test Run By	Date
	Carbon	C _T	- <u>(</u> -	_C _I	c _o		414 8474 48		
m L.	NH3-N	Dilut	ion	%T	Chart	PPM		* I Section and Company of the Company	
		•	-			-			
		2	477			(Second of Description Assessment			
						No. of Parliaments			
	pH							******	
	O r tho	Dilut	ion	<u>%T</u>	Graph	РРМ			Market a property of the state of
1		F	 ,	****					
					-				
						a returning god town			
	_SS	No.	Vol.	Wt.Dry	a designation of the second	Tare-Dry W		John	11-16-
		130	Ind	12985	17.2509	476 2906 166	47.6	00	
		725	5 ml	17.541	17.256	2906	58/1	20	
		710	of me	11/3/1	15/1/21	166	41.	500	
	OTHER(SPEC	IFY):_				The state of the s			

5.8 Springfield Ozark Hardwood

November 8, 1972

Ozark Hardwood Company 1412 West Florida Street Springfield, Missouri

Dear Sirs:

We are recently in receipt of a copy of a letter to you from the City of Springfield in regard to your discharge of water contaminants from your property. Please be advised that Sec. 204.051 of the Missouri Clean Water Law states that is unlawful to operate a water contaminant source without a permit from the Commission. Your company does not have the necessary permit for the discharge described by the City.

We feel, after review of the dates in the City's letter for prevention of the present discharge, that prompt and sound action is not being taken by your company. We strongly recommend that you cooperate fully with the City of Springfield in a prompt solution to your pollution problems. We are requesting the City of Springfield to keep us advised of your compliance with the schedule date of November 30, 1972, as well as your adherence to that schedule in an abatement program.

Yours truly,

Charles S. Decker, E.I.T. Regional Engineer Springfield Regional Office Missouri Clean Water Commission

CSD/cg

C.C. Central Office ATTN: Charles Stiefermann

Jerry Croy, Enforcement Officer

Harry Criswell., City of Springfield

Dick Paul, Investigation Section, U.S. Army Corps of Engineers, Little Rock

Ken. H. Christgen, President

November 2, 1972

Ozark Hardwood Company 1412 West Florida Street Springfield, Missouri 65803

Dear Sirs:

On May 11, 1972, you were contacted by personnel from this office and by the Environmental Protection Agency concerning the discharge of pollutants from your property. The source for these pollutants seems to be a building where wood is steam treated. Liquid discharged from this building runs across your property to the west and down a concrete channel to the stream. You were informed at that time that this discharge was not permissable. Samples were taken of the discharge and the results of the analyses are enclosed. Apparently, a shallow earthen dike was erected in an attempt to contain the discharge on your property. Inspections recently (October 2, October 16, October 30, October 31, 1972) indicate that a significant quantity of waste is still being discharged. This is a violation of Section 30 of the City Code, the Missouri Water Quality Standards, and the Federal Harbors and Refuse Act.

It is my suggestion that you prepare a timetable or schedule for abatement of your water quality problems. You should present a copy of this schedule to this office by November 30, 1972.

If we can be of any assistance to you, or can answer any questions, please do not hesitate to call.

Yours very truly,

Charles H. Criswell Chemist and Aquatic Biologist Industrial Waste Surveillance & Investigation

CHC:cc

ccs: Mr. Ken H. Christgen, President

Mr. Phillip S. Platter, Secretary

Mr. Daniel W. Duncan, Treasurer

Mr. Steve Decker, Regional Engineer, Missouri Clean Water Commission

Mr. Dick Paul, Investigation Section, U.S. Army Corps of Engineers

5-11-72 14:45 Sample S-26-601CC-Ozark Hardwood

Carbon, total	3,610 mg/l
Carbon, inorganic	108 mg/l
Carbon, organic	3,502 mg/1
Biochemical Oxygen Demand	4,450 mg/1
Suspended Solids	620 mg/l
Nitrogen, Ammonia, as mg/l N	139.50 mg/1
Phosphate, as mg/l PO ₄	9.50 mg/l
рН	6.31

Sample was highly colored

CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

ATTENTION OF Everett Balk

DATE March 9, 1972

DEPARTMENT P. W. - Sanitary Services

Re: Industrial Discharge Into Storm Sewers

Euch & Kansus	Sample I. D.	B.O.D.	s.s.	<u>NH</u> 3-N	PO4-3	pH
更	S - 01 - 562c	445	56	1.10	0.64	6.9
West & Kansus	S - 02 - 73 (5150	325	26.50 Ozark	0.75 Hardwoo	6.3 d 12

SIGNE

1412 W. FCORIDA

H. Criswell, Chemist

Feb. 31, 1972 Corson & Lyman

During an investigation in the Frisco Yards a black substance was observed as an influent coming into the east part of the yards at the head of N. Wilson Creek. Samples were taken and the problem was traced to drainage from Ozark Hardwood's yard where logs and lumber are stored. A lab report showed an extremely high BOD and the effluent from this firm was resampled. Results have not been obtained at this timm. (3-1-72)

Ozark Hardwood Co.
Ken H. Christgen, Pres. (r. St. Joseph Mo.)
Phillip S. Platter, Sec.
Daniel W. Duncan, Treas. (r. St. Joseph Mo.)
1412 W. Florida St.
866-0879

inspections 2-29-72 5-11-72 10-2-72 10-16-72 10-30-72 10-31-72